



Sample Building Inspection Report



Property Address: xxxxxxxx

Inspection Date: 10 January 2024

Report Date: 12/1/2024

Prepared For: [Title]

Prepared By: F Home Inspection

Frank Guo

Inspector: Certified Inspector



I would like to take this opportunity to thank you for choosing F Home Inspection as your building inspector!

'Choosing the right home inspector can be difficult. Unlike most professionals you hire, you probably won't meet me until our appointment. Furthermore, different inspectors have varying qualifications, equipment, experience, reporting methods, and pricing. Ultimately, a thorough home inspection depends heavily on the individual inspector's own effort. If you honor me by permitting me to inspect your new home, I guarantee that I will give you my very best effort. This, I promise you.'

- Frank Guo



Contents

- 01 Inspection Traffic Lights
- 02 Summary of Inspection
- 03 General
- 04 Limitations and conditions
- 05 Glossary
- 06 Restriction
- 07 Site
- 08 Exterior
- 09 Roof
- 10 Roof space
- 11 Subfloor
- 12 Interior
- 13 Plumbing
- 14 Electrical
- 15 Garage
- 16 Moisture
- 17 Certificate of Inspection

01. INSPECTION TRAFFIC LIGHTS

Green Traffic light



The items we have listed in GREEN, are what we have deemed as a low or no level of concern or recommendations.

Orange Traffic Light



The items we have listed in Orange in the report are what we are deemed as moderate level of concern associated with the building element, prompting caution, further investigation and/or repair be considered but not significant or urgent.

Red Traffic Light



The items we have listed in RED in the report are what we have deemed the major/significant defects in the property or a safety concern. It is recommended that these defects should be investigated further as soon as possible.

02. SUMMARY OF INSPECTION

Please read this entire report and not just rely on the summary to highlight any areas of concern. There still could be information and defects that are not listed in the summary that you may want to be aware of.

This report focuses on what we see as the nine main areas of concern for our clients when buying property. These areas are:

1. Site 2. Exterior 3. Roof 4. Roof space, 5. subfloor, 6. Interior 7. Plumbing 8. Electrical 9. Garage

Below is a summary of the highest concern level for each focus area and recommendations. Please refer to the focus area for further details.

<div>1.Site</div> <div>G</div>	<div>4.Roof space</div> <div>G</div>	<div>7. Plumbing</div> <div>G</div>
<div>2.Exterior</div> <div>O</div>	<div>5.Subfloor</div> <div>N/A</div>	<div>8. Electrical</div> <div>G</div>
<div>3.Roof</div> <div>O</div>	<div>6. Interior</div> <div>G</div>	<div>9. Garage</div> <div>G</div>

Overall, the property inspected appears to be in AVERAGE CONDITION for its age, construction type, and materials used in comparison with similar properties of the same age. The defects/risks observed, and recommendations are detailed in the report.

The key areas include the following:

Site

Cracks were sighted on the path and driveway from general settlement and movement over the years. Maintenance is recommended to prevent ongoing damage.

It is recommended that any vegetation touching the cladding is removed to help prevent the chance of moisture ingress in the future.

Exterior

There was a crack in the corner of the wall on the right side of the property. Maintenance and repair are recommended to reduce further damage to the wall cladding system.

There was a corner crack on the concrete foundation on the right side of the property. Regular monitoring and maintenance are recommended to reduce further damage.

Roof

There were cracks on the pointing and collars, and some collars were missing. Maintenance and repair are recommended to reduce further damage to the roof system.

3 pieces of tiles started to crack in the middle. Repair is recommended to reduce further damage to the roof or water penetration issues.

Several tiles' corners were cracked which might lead to further damage to the tile. Maintenance and repair are recommended.

There were lichen and moss on the roof which might cause damage to the roof. Cleaning and regular maintenance are recommended.

One area of the fascia had corrosion. Maintenance is recommended to reduce further damage.



Report Property Address: xxxxxxx

03. GENERAL

Weather Conditions at the time of the inspection:

Sunny

Recent weather conditions:

Sunny

Date and time of inspection:

10 January 2024

Building Furnished:

Yes

Onsite attendees:

Building inspector, realtor, and client

Did the homeowner, Agent or representation disclose any known issues to the property?

No

04. LIMITATIONS AND CONDITIONS

1. This report and inspection are in accordance with F Home Inspection Agreement terms and conditions.
2. F Home Inspection (FHI) will perform a building inspection for the specific purposes of assessing the general condition of the building and identifying defects that are readily apparent at the time of inspection based on the limited visual, non-invasive inspection. No responsibility is accepted in the event that the Report is used for any other purpose.
3. Unless otherwise noted in this Agreement or not possible, the Report is based on a limited visual, above ground, non-invasive inspection of the standard systems and components of the building. FHI does not open up, uncover or dismantle any part of the building as part of the inspection or undertake any internal inspection of the building. The procedure for the inspection will not comply fully with NZS 4306:2005. New Zealand Standard Residential Property Inspection as there may be areas that an inspector cannot check or cover at the time of inspection or are not covered in NZ4306.2005 as this is a guide only.
4. The Report is a guide only (as per New Zealand Standards) and not a guarantee or warranty as to the state of the building or any product, system, or feature in the building.
5. Areas of the building that the inspector believes to be potential problem areas for moisture ingress are checked with a non-invasive moisture meter. Rotting of timber framing and/or the presence of toxic molds, however, can only be determined by invasive testing which requires the removal of wall linings. This cannot be done without the written consent of the owner and is outside the scope of the Report. The Report is not a specialist weathertightness report and is a Visual Weather Tightness condition report only.

FHI accepts no responsibility or liability for any omission in its inspection or the Report related to defects or irregularities which are not reasonably visible at the time of the inspection, or which relate to components of the building:

- which are below ground, or which are concealed or closed behind finished surfaces (such as plumbing, drainage, heating, framing, ventilation, insulation or wiring).
- which required the moving of anything which impeded access or limited visibility (such as floor coverings, furniture, appliances, personal property, vehicles, vegetation, debris, or soil) – FHI does not move owner/occupier items for the purposes of the inspection.
- to which access is not reasonably and safely available to carry out a visual inspection. This may include roofs, subfloor areas and ceiling cavities and high, constricted, or dangerous areas for which inspection is not permitted by Occupational Safety and Health regulations.

In addition, the customer accepts that FHI will not detect some defects because: the defect may only occur intermittently; the defect has been deliberately concealed; or we have been given incorrect information by the customer or any third party. If you believe that any of these circumstances apply, then you should immediately contact us to try and resolve the problem.

Any area, system or component of the building or any item, feature or system not specifically identified in the Report as having been inspected was not included in the scope of the inspection. This includes the condition and location of any special features or services, underground services drainage or of any systems including electrical, plumbing, gas, or heating except as otherwise may be described in the Report. On request, specialist inspections can be arranged of weathertightness or structure or of any systems including electrical, plumbing, gas, or heating. Descriptions in the Report of systems or appliances relate to the existence of such systems or appliances only and not the adequacy, efficiency or life expectancy of such systems or appliances.

6. The Report:
 - is not a structural survey, engineer's report, weathertightness inspection or a report on the building's seismic safety. FHI can assist with arranging such specialist third party inspections upon request.
 - does not assess compliance with the requirements of any legislation (including any act, regulation, code or by-law) unless otherwise stated.
 - is not a geotechnical, site or environmental report. FHI makes no representation as to the existence or absence of any or "hazard" (as defined in the Health and Safety in Employment Act) or any "hazardous substance", "natural



Report Property Address: xxxxxxx

hazard” or “contaminant” (as those terms are defined in the Resource Management Act) in the building or property.

7. FHI has not undertaken any title search and assumes all improvements are within the legal boundaries of the property. No survey of the property or any search for information held by the territorial authority or any other relevant authority has been undertaken. It is recommended that the customer conducts his own Land Information Memorandum or Council property file search.
8. If the property is a Unit Title property, the inspection and Report is limited to the actual unit and any accessory unit(s) and does not extend to the remainder of the building or the common areas. FHI recommends the customer obtain a copy of the financial statements and minutes from meetings of the Body Corporate to establish the history of the inspected property under such Body Corporate.
9. Our responsibility in connection with this Report is limited to the customer to whom the Report is addressed and to that customer only. FHI disclaim all responsibility and will accept no liability to any other party without first obtaining our written consent of us. Any third party acting in or relying on this report, in whole or in part does so at his or her own risk. FHI reserves the right to alter, amend, explain, or limit any information given to any other party.
10. No Liability shall be accepted on an account of failure of the Report to notify any problems in the area(s) or section(s) of the subject property physically inaccessible for inspection, or to which access for inspection is denied by or to the Inspector (including but not limited to or any area(s) or section(s) so specified by the Report).
11. Should any dispute arise as a result of the inspection or the Report, it must be submitted to FHI in writing as soon as practically possible but in any case, within ten working days of discovery. The customer agrees that in the event of a dispute, the contents of the Report may not be used to satisfy any terms of a sale and purchase agreement until the disagreement/dispute has been resolved. In the event the customer nevertheless enters into an unconditional agreement for purchase of the subject property or makes an existing agreement unconditional prior to resolution of the dispute, the customer shall be deemed to have waived the customer’s rights to continue with and/or make any future claim against FHI in relation to that matter. Any claim relating to the accuracy of the Report, in the form of errors or omissions is limited to the failure on the part of FHI to follow the Standards of Practice of the New Zealand Standard; NZS 4306:2005 Residential Property Inspection (a copy can be made available for viewing if required). Except in the case of an emergency, the customer further agrees not to disturb, repair, replace or alter anything that may constitute evidence relating to the dispute or claimed discrepancy before FHI has had an opportunity to re-inspect and investigate the claim. The Customer understands and agrees that any failure to notify FHI or permit FHI to re-inspect as stated above shall be deemed to be a waiver of the customer’s rights to continue with and/or make any future claim against FHI in relation to that matter.
12. Nothing contained in these terms and conditions shall be deemed to exclude or restrict any rights or remedies that the customer may have under the Consumer Guarantees Act 1993 or otherwise at law.
13. If any provision in these terms and conditions is illegal, invalid, or unenforceable, such provision shall be deemed to be excluded or read down to the extent necessary to make the provision legal, valid or enforceable, and the remaining provisions of these terms and conditions shall not be affected.
14. If a court declares any provision of this Agreement invalid, the remaining provisions remain in effect. This Agreement represents our entire agreement; there are no terms other than those set forth herein. All prior discussions are merged into this Agreement. No statement or promise by us shall be binding unless reduced to writing and signed by one of our authorized officers. Any modification of this Agreement must be in writing and signed by you and by one of our authorized officers. This Agreement shall be binding upon and enforceable by the parties and their heirs, executors, administrators, successors, and assignees.

05. GLOSSARY

Fascia boards and barge boards: Is a board fastened to the projecting gables of a roof to give them strength and mask, hide and protect the otherwise exposed end of the horizontal timbers or purlins of the roof to which they were attached.

Soffit/Eaves: The exposed under surface of any exterior overhanging section of a roof eave.

Cladding: The exterior wall claddings is the application of one material over another to provide a skin or layer intended to control the infiltration of weather elements, or for aesthetic purposes. Cladding does not necessarily have to provide a waterproof condition but is instead a control element.

Trim: (Skirting, scotia and architraves) the finishing timbers around the floor and ceiling and the timbers around windows and doors.

Hardware: Door handles, door hinges, bolts, latches, window hardware, screws, switch plates, and doorknockers.

Gully Trap: A gully trap is a basin in the ground with a water seal to prevent foul odours of the sewer reaching the surface.

Flashings: Are placed around discontinuities or objects which protrude from the roof of a building (such as pipes and chimneys, or the edges of other roofs) to deflect water away from seams or joints.

Bearer and Joists: A joist, in architecture and engineering, is one of the horizontal supporting members that run from wall to wall, wall to beam, or beam to beam to support a ceiling, roof, or floor. It may be made of wood, steel, or concrete. Typically, a beam is bigger than, and is thus distinguished from, a joist. Joists are often supported by beams and are usually repetitive.

GIB: (Drywall), also known as plasterboard or gypsum board, is a panel made of gypsum plaster pressed between two thick sheets of paper. It is used to line interior walls and ceilings.

06. RESTRICTIONS

EXPLANATIONS	Areas not inspected including reasons were:
	<ul style="list-style-type: none"> - Furniture, closed wardrobes/cupboards, and storage restricted full view of the interior in some areas,
	<ul style="list-style-type: none"> - Vegetation and storage restricted full view of the exterior decking, cladding and windows in some areas, - Solar panels restricted views of the roof covering above the kitchen and bathroom area,
	<ul style="list-style-type: none"> - Insulation was covering the ceiling linings, also there was insufficient clearance to access the corners of the roof space,
	<ul style="list-style-type: none"> - Vegetation restricted views of the fencing and detached shed, the garage and detached shed also had storage in them restricting views of the wall and floor areas
	Areas to which access should be gained, or fully gained, are:
	<ul style="list-style-type: none"> - Roof space, - Internally; storage/furniture, - Garage storage, - Walls & fencing, - Roof exterior

07. SITE

INSPECTION FOCUS

This inspection is not intended to address or include any geological conditions or site stability information. We do not comment on coatings or cosmetic deficiencies and the wear and tear associated with the passage of time, which would be apparent to the average person. However, cracks in hard surfaces can imply the presence of expansive soils that can result in continuous movement, but this can only be confirmed by a geological evaluation of the soil. Any reference to grade is limited to only areas around the exterior of the exposed areas of foundation or exterior walls. We do not evaluate whether it is a flood / earthquake prone site. We cannot determine drainage performance of the site or the condition of any underground piping, including subterranean drainage systems and public water and sewer service piping or septic systems. Decks and porches are often built close to the ground, where no viewing or access is possible. Any areas too low to enter or not accessible are excluded from the inspection. We do not evaluate any detached structures such as storage sheds and stables, nor mechanical or remotely controlled components such as driveway gates. We do not evaluate or move landscape components such as trees, shrubs, fountains, ponds, statuary, pottery, fire pits, patio fans, heat lamps, and decorative or low-voltage lighting. Any such mention of these items is informational only and not to be construed as inspected.

RESTRICTIONS

None.

7.1 ORIENTATION OF LIVING SPACES

The living room was on the Northern side of the house.

7.2 SITE EXPOSURE, CONTOUR AND VEGETATION

The house was positioned on a near flat section. **It is recommended that any vegetation touching the cladding is removed to help prevent the chance of moisture ingress in the future.**



7.3 RETAINING WALLS

No visible issues were found.

7.4 PATHS AND DRIVEWAYS: ARE ALL AREAS FREE OF SUBSIDENCE/CRACKING, AND ARE THEY UNDAMAGED AND SAFE TO WALK UPON?

Cracks were sighted on the path and driveway from general settlement and movement over the years. Maintenance is recommended to prevent ongoing damage.





7.5 STEPS AND HANDRAILS; ARE ALL AREAS FREE OF SUBSIDENCE, TRIPS HAZARDS AND SAFE TO WALK UPON?

No visible issues were found.



7.6 FENCING: DO GENERAL FENCES APPEAR IN REASONABLE CONDITION FOR THEIR AGE?

No visible issues were found.



7.7 SURFACE WATER; DOES RAINWATER DRAIN EFFECTIVELY AND NOT POND AGAINST STRUCTURES?

No visible issues were found. - The paving or paths around the walls appeared to be adequately drained away from the foundation. There was no visible evidence of excess ponding or falling towards the home's walls at the time of the inspection.

08. EXTERIOR

INSPECTION FOCUS

This includes inspection of the external surfaces of the building like cladding, other systems attached to it and exterior features. There may be restrictions to inspection like stored items and vegetation which will be mentioned in the report. We do not move anything for inspection.

RESTRICTIONS

N/A

8.1 CONSTRUCTION TYPE

Timer framed.

8.2 CLADDING MATERIAL

Brick.

8.3 ARE ALL WALLS/WALL CLADDING FREE OF DEFECT/DAMAGE, AND IS THE PAINT/COATING MAINTAINED?

There was a crack in the corner of the wall on the right side of the property. Maintenance and repair are recommended to reduce further damage to the wall cladding system.




8.4 DOES THE WALL CLADDING HAVE SUITABLE FLASHINGS AND DAMP-PROOF COURSE, AND IS IT FREE OF DAMPNESS

No visible issues were found.

8.5 FOR DOORS & WINDOWS, DO SUITABLE FLASHINGS, MOULDINGS, AND SILLS EXIST & ARE THEY FREE OF DEFECT/DAMAGE?

No visible issues were found - The window and door units appeared in good condition for their age.

**8.6 FOUNDATION/BALCONIES/VERANDAHS/PATIOS/DECKS/SUSPENDED FLOORS/BALUSTRADES: DO THEY APPEAR IN REASONABLE CONDITION FOR THEIR AGE?**

There was a corner crack on the concrete foundation on the right side of the property. Regular monitoring and maintenance are recommended to reduce further damage.



F HOME INSPECTION

Report Property Address: xxxxxx



09. ROOF

INSPECTION FOCUS

We generally do not walk on the roof as it can cause roof surface damage. In some cases, we do walk on the roof where it won't cause damage and is safe to do so, where a closer inspection is preferred. Every roof will wear differently relative to its age, number of layers, quality of material, method of application, exposure to weather conditions, and the regularity of its maintenance. We can only offer an opinion of the general quality and condition of the roofing material. The inspector cannot and does not offer an opinion or warranty as to whether the roof leaks or may be subject to future leakage. Although roof condition can be evaluated, it is virtually impossible for anyone to detect a leak except as it is occurring or by specific water tests, which are beyond the scope of a standard home inspection. Even water stains on ceilings or on framing within attics will not necessarily confirm an active leak without some corroborative evidence, and such evidence can be deliberately concealed. We evaluate every roof conscientiously, but we will not predict its remaining life expectancy, or guarantee that it will not leak. Naturally, the sellers or the occupants of a residence will generally have the most intimate knowledge of the roof and of its history. Therefore, we recommend that you ask the sellers about it. We do not inspect attached accessories including but not limited to solar systems, antennae, and lightning arrestors except for their connection to roof.

RESTRICTIONS


N/A

9.1 ROOF MATERIAL

Concrete Tile.

9.2 IS THE ROOF FREE OF CRACKED AND BROKEN/DECAYED ETC?

There were cracks on the pointing and collars, and some collars were missing. Maintenance and repair are recommended to reduce further damage to the roof system.



3 pieces of tiles started to crack in the middle. Repair is recommended to reduce further damage to the roof or water penetration issues.



Several tiles' corners were cracked which might lead to further damage to the tile. Maintenance and repair are recommended.



There were lichen and moss on the roof which might cause damage to the roof. Cleaning and regular maintenance are recommended.



9.3 FLASHING CONDITION

No visible issues were found.

9.4 VENTS & FLUES; DO THE SERVICES AND FLASHINGS APPEAR WATERTIGHT?

No visible issues were found.



9.5 EAVES, FASCIA, AND SOFFITS

One area of the fascia had corrosion. Maintenance is recommended to reduce further damage.



9.6 GUTTERS AND DOWNPIPES

No visible issues were found.



10. ROOF SPACE

INSPECTION FOCUS

There is a minimum access requirement for inspecting the attic space in the inspection standard and it is not possible to access all parts of the attic. We do not enter the attic if we feel it is unsafe to do so. We identify the type of roof structure, alterations / defects, insulation condition, wiring, roof underlay etc., The inspector cannot and does not offer an opinion or warranty as to whether the roof leaks or may be subject to future leakage. Although roof condition can be evaluated, it is virtually impossible for anyone to detect a leak except as it is occurring or by specific water tests, which are beyond the scope of our service. Even water stains on ceilings or on framing within attic will not necessarily confirm an active leak without some corroborative evidence, and such evidence can be deliberately concealed. Naturally, the sellers or the occupants of a residence will generally have the most intimate knowledge of the roof and of its history. Therefore, we recommend that you ask the sellers about it.

RESTRICTIONS

N/A

10.1 ACCESSIBILITY


The attic hatch is in the garage.

10.2 IS THE UNDERSIDE OF THE ROOF FREE OF WATER STAINING OR OBSERVED DAYLIGHT?

No visible issues were found.

10.3 DOES THE FRAMING APPEAR TO BE FREE OF DEFECTS/DECAY/CORROSION OR OTHER DAMAGE?

No visible issues were found.



10.4 ROOFING PAPER; IS THE BUILDING PAPER IN PLACE, AND IS IT FREE OF HOLES/TEARS OR OTHER DAMAGE?

No roof paper.



10.5 INSULATION; IF INSULATION EXISTS ON THE UPPER SURFACE OF THE CEILING, DOES IT FULLY COVER THE CEILING AREA?

No visible issues were found.



10.6 INSECTS, VERMINE, BIRDS, RODENTS?

No signs of pest intrusion.

11. SUBFLOOR

INSPECTION FOCUS

This inspection is not a structural inspection. All structures are dependent on the soil beneath them for support, but soils are not uniform. In accordance with the inspection standard, we identify foundation types and look for any evidence of structural deficiencies / alterations. However, minor cracks or deteriorated surfaces are common in many foundations, and most do not represent a structural problem. If major cracks are present along with bowing, we routinely recommend further evaluation be made by a qualified structural engineer. All exterior grades should allow for surface and roof water to flow away from the foundation. Areas hidden from view by finished walls or stored items cannot be judged and are not a part of this inspection. We will certainly alert you to any suspicious cracks if they are clearly visible. However, we are not specialists, and in the absence of any major defects, we may not recommend that you consult with a foundation contractor, a structural engineer, or a geologist, but this should not deter you from seeking the opinion of any such expert. We also routinely recommend that inquiry be made with the seller about knowledge of any prior foundation or structural repairs.

N/A



12. INTERIOR

INSPECTION FOCUS

Our inspection of living space includes the visually accessible areas of walls, floors, cabinets, and closets, and the testing of a representative number of windows and doors. We do not evaluate window treatments, move furnishings or possessions, lift carpets or rugs, empty closets, or cabinets, nor comment on cosmetic deficiencies. Floor covering damage or stains may be hidden by furniture, and the condition of floors underlying floor coverings is not inspected. Determining the condition of insulated glass windows is not always possible. Check with owners for further information. We do not inspect the fireplace or chimney interiors. All fireplaces should be cleaned and inspected on a regular basis to make sure that no cracks have developed. Testing or identifying the source of environmental pollutants or odours (including but not limited to lead, mold, allergens, odors from household pets and cigarette smoke) is beyond the scope of our service.

RESTRICTIONS

Furniture, closed wardrobes/cupboards, and clutter restricted full view of the interior in some areas.



12.1 DOORS (INTERIOR)

Door inspection includes examination for proper installation, operation, and condition. A representative number of interior doors and all exterior doors were operated.

12.2 WINDOWS

Window inspection includes examination for proper installation, operation, and condition. A representative number of windows were operated.

12.3 MAIN FLOOR, WALL, AND CEILING





Floors are covered with carpet in general. Walls: Plaster board. Ceilings: Plaster board.

12.4 ENTRY / HALLWAYS

Condition: Photo showing overview of the area.



Moisture Readings: Low moisture readings were recorded indicating dry conditions.








12.5 LIVING ROOM

Condition: Photo showing overview of the area.



Moisture Readings: Low moisture readings were recorded indicating dry conditions.



12.6 KITCHEN

Condition: Photo showing overview of the area.





Are the sinks/taps free of defects, leaks and does the water supply operate correctly?
Yes - The sink and taps appeared free from defect and the water supply was operating correctly.

Is the sealing at counter to wall junction in good condition?
Yes.




Moisture Readings: Low moisture readings were recorded indicating dry conditions.



12.7 MASTER BEDROOM

Condition: Photo showing overview of the area.




Moisture Readings: Low moisture readings were recorded indicating dry conditions.




Are taps, toilet free of leaks, and does the water supply operate correctly?

Yes - The taps appeared free from leaks and the water supply was operating correctly.



Moisture Readings: Low moisture readings were recorded indicating dry conditions.






12.8 BEDROOM 2

Condition: Photo showing overview of the area.



Moisture Readings: Low moisture readings were recorded indicating dry conditions.




12.9 BEDROOM 3

Condition: Photo showing overview of the area.





Moisture Readings: Low moisture readings were recorded indicating dry conditions.






12.10 ROOM 4

Condition: Photo showing overview of the area.



Moisture Readings: Low moisture readings were recorded indicating dry conditions.





12.11 BATHROOM/WC

Bathroom Condition: Photo showing overview of the area.




Moisture Readings: Low moisture readings were recorded indicating dry conditions.








Toilet Condition: Photo showing overview of the area.



Moisture Readings: Low moisture readings were recorded indicating dry conditions.





12.12 LAUNDRY

Condition: Photo showing overview of the area.



Moisture Readings: Low moisture readings were recorded indicating dry conditions.



13. PLUMBING

INSPECTION FOCUS

Water quality or hazardous materials (lead) testing is available from local testing labs, and not included in this inspection. All underground piping related to water supply, waste, or sprinkler use are excluded from this inspection. Leakage or corrosion in underground piping cannot be detected by a visual inspection, nor can the presence of mineral build-up that may gradually restrict their inner diameter and reduce water volume. Plumbing components such as gas pipes, potable water pipes, drain and vent pipes, and shut-off valves are not generally tested. The inspector cannot state the effectiveness or operation of any anti-siphon devices, automatic safety controls, water conditioning equipment, fire and lawn sprinkler systems, on-site water quality and quantity, on-site waste disposal systems, foundation irrigation systems, spa and swimming pool equipment, solar water heating equipment, or observe the system for proper sizing, design, or use of materials.

Water heater is only inspected visually for leaks, supports, corrosion etc., where accessible and its response to hot water demand from taps. The adequacy or efficiency is not tested which is beyond the scope of this standard inspection.

RESTRICTIONS



No

13.1 WATER SOURCE

The home water was supplied from a public source.

13.2 HOT WATER CYLINDER

Closet in hallway.



13.3 DRAIN / WASTE / VENT PIPES NOTES

The General Home Inspection is a visual inspection of the home systems and their visible, accessible components. The home inspector evaluates drainpipes by operating and observing each operable home plumbing fixture to ensure proper drainage at each fixture at the time of the inspection. Blockages can occur between the time the home is inspected and the time you move in, sometimes due to cleaning activities. Blockages will eventually occur, usually relative in severity to the age of the plumbing system, and will range from minor blockages of branch lines, or at the traps beneath sinks, tubs, and showers, to major blockages in the main sewer line. Minor blockages are usually easily cleared, either by chemical or mechanical means or by removing and cleaning the traps. The Inspector recommends that you ask the sellers if they have ever experienced any drainage problems. If the home is older, you may wish to have the main waste line video-scanned, as replacement can be expensive.

14. ELECTRICAL

INSPECTION FOCUS

We are not electricians and in accordance with the inspection standard, we only test a representative number of switches and outlets and do not perform load-calculations to determine if the supply meets the demand. We do not open the panel cover and we check the main panel visually and make our comments. Any electrical repairs or upgrades should be made by a registered electrician. Inoperative light fixtures often lack bulbs or have dead bulbs installed. Any ancillary wiring or system that is not part of the primary electrical distribution system is not part of this inspection but may be mentioned for informational purposes only, including but not limited to low voltage systems, security system devices, heat detectors, carbon monoxide detectors, telephone, security, cable TV, intercoms and built in vacuum equipment.

RESTRICTIONS

No.

14.1 LIGHTS; WERE THE LIGHTS SWITCHES TESTED AND WORKING?

A representative number of interior and exterior wall switches responded to testing at the time of the inspection.

14.2 WERE THE POWER POINTS TESTED AND WORKING?

A representative number of power points responded to testing at the time of the inspection.



14.3 METER BOARD POSITION

Position: Back of house, Smart meter



14.4 OVERHEAD CABLES; WERE THE OVERHEAD WIRES CLEAR FROM TREES?

No issues were found.

15. GARAGE

INSPECTION FOCUS

Inspection of garage may be limited by the parked vehicles. Garages are designed as non-habitable spaces and are inspected accordingly.

RESTRICTIONS

N/A

15.1 DOORS

Metal rolling door was functional.

15.2 GENERAL CONDITIONS

Condition: Photo showing overview of the area.



Moisture Readings: Low moisture readings were recorded indicating dry conditions.



16. MOISTURE

INSPECTION FOCUS

Any moisture concentrations detected during this inspection will be included within this report. We use Trotec T660 non-invasive moisture meter to perform our moisture testing.

Range Of Moisture Reading (Digits)

- 1-40 Dry
- 41-80 Damp
- 81 & above Wet



The displayed measurement values are not qualified moisture measurement in accordance with or applicable professional regulations. The measured values are only to be interpreted as indicators (dry, damp, and wet).

These readings are indicative only and vary from property to property and dependent on the weather and other conditions at the time of inspection. Sometimes the moisture meters may show false positive readings due to the presence of metals underneath. Damp and wet readings will be notified in the report and further intrusive destructive testing may be required to examine the extent of moisture intrusion / damage which is not under the scope of this standard inspection. Infrared thermography may be performed if conditions favour, and any abnormalities will be confirmed with moisture meter and reported.

17. CERTIFICATE OF INSPECTION

Certificate of Inspection in accordance with NZS 4306:2005

Client: [Title]

Site Address: xxxxxxx

Inspector: Frank Guo

Company: F Home Inspection

Qualifications: Certified Building Inspector

Report type: Residential Building Inspection Report

Date of Inspection: 10 January 2024

Areas Inspected: Site, Subfloor, Exterior, Roof, Roof space, Interior, Services,
Accessory units Ancillary Spaces and Buildings

Certification

I hereby certify that I have carried out the inspection of the property at the above address in accordance with NZS 4306:2005 Residential Property Inspection, and I am competent to undertake this inspection.



On behalf of F Home Inspection

Date: 12/1/2024

An inspection carried out in accordance with NZS4306:2005 is not a statement that a property complies with the requirement of any Act, regulation or bylaw, nor is the report a warranty against any problems developing after the date of the property report. Refer NZS4306:2005 for full details.